UNIVERSITI TEKNOLOGI BRUNEI

TARIKH TUTUP/

CLOSING DATE: **23 MEI 2019 9.00 PAGI**

BIL. SEBUTHARGA/QUOTATION NO.: UTB/QTN/2019-2020/01/MTC

TARIKH / DATE: **08 MEI 2019**

NOTA*
SILA HANTAR SEBUTHARGA TERUS KEPADA:
PEJABAT KEWANGAN
1F.34 TINGKAT 1 BLOK F
UNIVERSITI TEKNOLOGI BRUNEI
LEBUHRAYA TUNGKU
GADONG BE1410
NEGARA BRUNEI DARUSSALAM

QUOTATION TITLE: FOR THE PLANNED PREVENTATIVE MAINTENANCE, CALIBRATION SERVICE AND REPAIR WORKS ON INSTRON MACHINES FOR MATERIAL TESTING CENTRE, UNIVERSITI TEKNOLOGI BRUNEI.

NO.	KETERANGAN / DESCRIPTION	KUANTITI/ QUANTITY	TAWARAN / OFFER	KADAR / RATE (B\$)	JUMLAH /AMOUNT (B\$)
	Job Scope for PM service for Instron 8505R8800MTL5063 hydraulic machines.				
1	* Check Instron hydraulic power supply * Check load frame, basic system and control pane * Checking of computer * Safety checks * Replacement of filters for the power pack	1 lot			
	Job Scope for PM service for Instron 8516R8800MTL5067 hydraulic machines.	57			
2	* Check Instron hydraulic power supply * Check load frame, basic system and control pane * Checking of computer * Safety checks * Replacement of filters for the power pack	1 lot			

UNIVERSITI TEKNOLOGI BRUNEI

	Job Scope for the PPM service for 5565H1640 Machine.			
3	* Checking of basic system and handset * Checking of crosshead and drive system including lubricating of columns and leadscrews * Checking of load weighing system, strain measurement system and other accessories. * Checking of computer. * Safety checks.	1 lot		
	Job Scope for the PPM service for 5584C3676 Machine.			
4	* Checking of basic system and handset * Checking of crosshead and drive system including lubricating of columns and leadscrews * Checking of load weighing system, strain measurement system and other accessories. * Checking of computer. * Safety checks	1 lot		

.....

UNIVERSITI TEKNOLOGI BRUNEI

		T						
	Repair works: - For Instron 5565H1640 * Supply and install of motor assembly * Supply and install of power amplifier * Repair of Ethernet Frame Interface and PC interface card	1 lot						
5	- For Instron 5584C3676 * Repair of Ethernet Frame Interface * Repair of PC and replace motherboard / Interface card to machine	1 lot						
	- For Instron 8516R8800MTL5067 * Supply and install of pressure gauge includes gauge washer and fitting adapter * Repair of main control panel and interface to PC	1 lot						
*Note: Contractors are advised to conduct visit at MTC before submission of quotation to familiarize with scope of the work involved.								
Comp	any Name:							
0	tion Well-time (original or 6 months)		Contact Person:					
Delivery Period: 2 weeks after receiving Purchase Order Warranty:			Contact Tel. No:					
			Designation:					
			Date:					
Installation:								

.....